

Thermo-Hygrometer

103-CTH/411-CTH

103-CTH

Big Display Thermo / Hygrometer with Clock
large 2 line LCD display.

- Temperature Range : -50 C~70°C (-58F~ 158°F)
- Temp. Accuracy : $\pm 0.5^{\circ}\text{C}$ (0~ 40°C) or $\pm 1\%$
- Humidity Range : 10% ~ 99% RH
- Humidity Accuracy : $\pm 3\%$ RH (50% ~ 80%) or $\pm 5\%$
- Battery : AAA 1.5V.
- Time / Temp / Humidity indicate.
- Temp, reading for °F & °C.
- MAX and MIN Temperature and Humidity Memory.
- Calendar with Alarm Clock.



411-CTH

THERMO / HYGROMETER with CLOCK

- Environment Comfort Display : "COMFORT", "WET", "DRY"
- Temperature Range : -20 C~ 70°C (-4°F~158°F)
- Accuracy : $\pm 1^{\circ}\text{C}$ (1.8°F)
- Humidity Range : 10% ~ 90%RH
- Humidity Accuracy : +5%
- Battery : AAA 1.5V
- Time / Temp / Humidity indicate
- Temp, reading for °F & °C
- MAX and MIN Temperature and Humidity Memory
- Calendar with Alarm Clock

